




FORM DP




Type	d
DP 250	M12x1,75
DP 630	M20x2,5




FORM DR






ANSI CLAMP





Pos	Description	Material	Qty
1	Ansi Clamp M10	CuZn40Pb2	1
2	Eye Bolt M10	CuZn40Pb2	1
3	Spring Washer	St37 zinc	1
4	Nut M10	CuZn40Pb2	1



Pos	Description	Material	Qty
1	Washer M12	St37 zinc ☐ A2-70 ☐	2
2	Bolt M12x65	St37 zinc ☐ A2-70 ☐	2
3	Connection Flag	CuZn40Pb2	1



Type	d1	b1	e1	e2	b2	e3	h	a1	l1	a2	s	g	z	D	w(kg)
FP 2000	M42x3	100	25	50	58	40	80	20	190	40	15	55	4	14	3.20
FP 3150	M48x3	120	30	60	68	45	80	20	210	40	15	55	4	14	4.35
FP 4500	M55x3	150	40	75	85	30	90	40	250	70	20	75	4	18	7.55



Type	Current A	b1	b2	b3	d1	d3	e1	e2	g	l1	l4	n	p	x1	x2	z	D
ER 1000	1000	60	45	36	M30x2	M10	17	26	40	135	95	60	10	17	26	2	14
FR 2000	2000	100	58	45	M42x3	M12	25	50	55	210	155	80	15	20	40	4	14
FR 3150	3150	120	68	58	M48x3	M12	30	60	55	230	175	80	15	20	40	4	14

Material: Copper or Brass
Surface : Tin plated or silver plated

